

NOTES:

- 1. IF "G" IS GREATER THAN ½" AT IT'S NARROWEST POINT, THEN A FULL CIRCLE SPACER OR "DUTCHMAN" MUST BE CUT AND PLACED IN THE GAP BEFORE THE SLEEVE IS USED TO CLOSE THE JOINT.

 2. THE "DUTCHMAN" SPACER SHALL BE CUT TO A WIDTH NO LESS THAN ½" LESS THAN THE NARROWEST WIDTH OF "G".

 3. EACH PIPE SPIGOT SHALL BE MARKED TO INDICATE THE POINT WHERE THE
- SLEEVE WILL BE PROPERLY CENTERED OVER THE POINT.
- 4. "FULL-CIRCLE" REPAIR CLAMPS ARE NOT APPROVED FOR JOINING PIPE.
- 5. IF "STEEL" SLEEVE IS USED, PROPERLY COAT BEFORE BACKFILLING.

	E: 12-2-05	NEW YEAR	APPROVED: DEW	DGS/DRN/CHKD: CMS	· · · · · · · · · · · · · · · · · · ·	
	DATE	2	<u></u>	_ 	<u>'</u>	
					NRR	
					8/08	

FULTON COUNTY STANDARD DETAIL 130 PIPE JOINING: USE OF SOLID SLEEVE

141 PRYOR ST. ATLANTA, GA. 30303 404-612-7400 FAX: 404-224-0498 FULTON COUNTY PUBLIC WORKS

RAWING NO